



Color-HP Printer replacement toner supplies

| Machine Type* | Xerox Part Number | Equivalent OEM Part Number | For Use In | OEM Stated Yield | Xerox Stated Yield |
|---------------------------|----------------------|-------------------------------|---|------------------------|--------------------------|
| LJ4600** | 6R941 | C9720A – Black | HP Color LaserJet 4600, 4600n, 4600dn, 4600dtn, 4600hdn, 4650, 4650n, 4650dn, 4650dtn, 4650hdn | 9,000‡ | 9,000‡ |
| LJ4600** | 6R942 | C9721A – Cyan | HP Color LaserJet 4600, 4600n, 4600dn, 4600dtn, 4600hdn, 4650, 4650n, 4650dn, 4650dtn, 4650hdn | 8,000‡ | 8,000‡ |
| LJ4600** | 6R943 | C9722A – Yellow | HP Color LaserJet 4600, 4600n, 4600dn, 4600dtn, 4600hdn, 4650, 4650n, 4650dn, 4650dtn, 4650hdn | 8,000‡ | 8,000‡ |
| LJ4600** | 6R944 | C9723A – Magenta | HP Color LaserJet 4600, 4600n, 4600dn, 4600dtn, 4600hdn, 4650, 4650n, 4650dn, 4650dtn, 4650hdn | 8,000‡ | 8,000‡ |
| LJ2500/LJ2800** | 6R1285 | C9700A/Q3960A Black | HP Color LaserJet 1500, 2500, 2550, 2800 Series | 5,000‡ | 5,000‡ |
| LJ2500/LJ2800** | 6R1286 | C9701A/Q3961A Cyan | HP Color LaserJet 1500, 2500, 2550, 2800 Series | 4,000‡ | 4,000‡ |
| LJ2500/LJ2800** | 6R1287 | C9702A/Q3962A Yellow | HP Color LaserJet 1500, 2500, 2550, 2800 Series | 4,000‡ | 4,000‡ |
| LJ2500/LJ2800** | 6R1288 | C9703A/Q3963A Magenta | HP Color LaserJet 1500, 2500, 2550, 2800 Series | 4,000‡ | 4,000‡ |
| LJ3500/LJ3550 LJ3700** | 6R1289 | Q2670A – Black | HP Color LaserJet 3500 Series, 3550 Series, 3700 Series | 6,000‡ | 6,000‡ |
| LJ3500/LJ3550** | 6R1290 | Q2671A – Cyan | HP Color LaserJet 3500 Series, 3550 Series | 4,000‡ | 4,000‡ |
| LJ3500/LJ3550** | 6R1291 | Q2672A – Yellow | HP Color LaserJet 3500 Series, 3550 Series | 4,000‡ | 4,000‡ |
| LJ3500/LJ3550** | 6R1292 | Q2673A – Magenta | HP Color LaserJet 3500 Series, 3550 Series | 4,000‡ | 4,000‡ |
| LJ3700** | 6R1293 | Q2681A – Cyan | HP Color LaserJet 3700 Series | 6,000‡ | 6,000‡ |
| LJ3700** | 6R1294 | Q2682A – Yellow | HP Color LaserJet 3700 Series | 6,000‡ | 6,000‡ |
| LJ3700** | 6R1295 | Q2683A – Magenta | HP Color LaserJet 3700 Series | 6,000‡ | 6,000‡ |
| LJ5500/LJ5550** | 6R1313 | C9730A – Black | HP Color LaserJet 5500 Series, 5550 Series | 13,000‡ | 13,000‡ |
| LJ5500/LJ5550** | 6R1314 | C9731A – Cyan | HP Color LaserJet 5500 Series, 5550 Series | 12,000‡ | 12,000‡ |
| LJ5500/LJ5550** | 6R1315 | C9732A – Yellow | HP Color LaserJet 5500 Series, 5550 Series | 12,000‡ | 12,000‡ |
| LJ5500/LJ5550** | 6R1316 | C9733A – Magenta | HP Color LaserJet 5500 Series, 5550 Series | 12,000‡ | 12,000‡ |

^{*}References Canon engine type. **Contains a smart chip to enable smart print functions.

[†]Yields declared in accordance with ISO/IEC 19752 Standard. ‡Yields declared in accordance with ISO/IEC 19798 standard.

Color-HP Printer replacement toner supplies

| Machine Type* | Xerox Part Number | Equivalent OEM Part Number | For Use In | OEM Stated Yield | Xerox Stated Yield |
|----------------------------|----------------------|-------------------------------|--|------------------------|--------------------------|
| CP4005** | 6R1326 | CB400A – Black | HP Color Printer 4005 Series | 7,500‡ | 7,500‡ |
| CP4005** | 6R1327 | CB401A – Cyan | HP Color Printer 4005 Series | 7,500‡ | 7,500‡ |
| CP4005** | 6R1328 | CB402A – Yellow | HP Color Printer 4005 Series | 7,500‡ | 7,500‡ |
| CP4005** | 6R1329 | CB403A – Magenta | HP Color Printer 4005 Series | 7,500‡ | 7,500‡ |
| LJ4700** | 6R1330 | Q5950A — Black | HP Color LaserJet 4700 Series | 11,000‡ | 11,000‡ |
| LJ4700** | 6R1331 | Q5951A – Cyan | HP Color LaserJet 4700 Series | 10,000‡ | 10,000‡ |
| LJ4700** | 6R1332 | Q5952A – Yellow | HP Color LaserJet 4700 Series | 10,000‡ | 10,000‡ |
| LJ4700** | 6R1333 | Q5953A – Magenta | HP Color LaserJet 4700 Series | 10,000‡ | 10,000‡ |
| LJ3800/LJ3600 CP3505** | 6R1338 | Q6470A – Black | HP Color LaserJet 3800 Series, 3600 Series, Color Printer 3505 Series | 6,000‡ | 6,000‡ |
| LJ3600** | 6R1339 | Q6471A – Cyan | HP Color LaserJet 3600 Series | 4,000‡ | 4,000‡ |
| LJ3600** | 6R1340 | Q6472A – Yellow | HP Color LaserJet 3600 Series | 4,000‡ | 4,000‡ |
| LJ3600** | 6R1341 | Q6473A – Magenta | HP Color LaserJet 3600 Series | 4,000‡ | 4,000‡ |
| LJ3800/CP3505** | 6R1343 | Q7581A – Cyan | HP Color LaserJet 3800 Series, Color Printer 3505 Series | 6,000‡ | 6,000‡ |
| LJ3800/CP3505** | 6R1344 | Q7582A – Yellow | HP Color LaserJet 3800 Series, Color Printer 3505 Series | 6,000‡ | 6,000‡ |
| LJ3800/CP3505** | 6R1345 | Q7583A – Magenta | HP Color LaserJet 3800 Series, Color Printer 3505 Series | 6,000‡ | 6,000‡ |
| LJ2600/1600** | 6R1410 | Q6000A – Black | HP Color LaserJet 2600, 1600 Series, CM1015mfp, CM1017mfp | 2,500‡ | 2,500‡ |
| LJ2600/1600** | 6R1411 | Q6001A – Cyan | HP Color LaserJet 2600, 1600 Series, CM1015mfp, CM1017mfp | 2,000‡ | 2,000‡ |
| LJ2600/1600** | 6R1413 | Q6002A – Yellow | HP Color LaserJet 2600, 1600 Series, CM1015mfp, CM1017mfp | 2,000‡ | 2,000‡ |
| LJ2600/1600** | 6R1412 | Q6003A – Magenta | HP Color LaserJet 2600, 1600 Series, CM1015mfp, CM1017mfp | 2,000‡ | 2,000‡ |
| CP1215** Available August | 6R1439 | CSS541A – Black | HP Color LaserJet CP1201, 1215, 1510, 1515n, CM 1300, 1320 MFP | 2,200‡ | 2,200‡ |
| CP1215** Available August | 6R1440 | CSS541A – Cyan | HP Color LaserJet CP1201, 1215, 1510, 1515n, CM 1300, 1320 MFP | 1,400‡ | 1,400‡ |
| CP1215** Available August | 6R1441 | CSS541A – Yellow | HP Color LaserJet CP1201, 1215, 1510, 1515n, CM 1300, 1320 MFP | 1,400‡ | 1,400‡ |
| CP1215** Available August | 6R1442 | CSS541A – Magenta | HP Color LaserJet CP1201, 1215, 1510, 1515n, CM 1300, 1320 MFP | 1,400‡ | 1,400‡ |

^{*}References Canon engine type. **Contains a smart chip to enable smart print functions.

 $[\]pm$ Yields declared in accordance with ISO/IEC 19752 Standard. \pm Yields declared in accordance with ISO/IEC 19798 standard.

Black-HP, Apple Printer replacement toner supplies

| Mαchine Type* | Xerox Part Number | Equivalent OEM Part Number | For Use In | OEM Stated Yield | Xerox Stated Yield |
|----------------------|----------------------|-------------------------------|--|------------------------|--------------------------|
| PX | 6R899 | HP92274A M2045GA | HP LaserJet 4L, 4ML, 4LC, 4P, 4MP, 4PJ, Apple Personal LaserWriter 300, 320 | 3,350‡ | 3,600‡ |
| EX | 6R903 | HP92298A M2473G/A | HP LaserJet 4, 4+, 4M, 4M+, 5, 5M, 5N Apple LaserWriter 16/600, Pro 600, 630 | 6,800‡ | 7,300‡ |
| EX Extended Yield | 6R904 | HP92298X M273G/A | HP LaserJet 4, 4+, 4M, 4M+, 5, 5M, 5N Apple LaserWriter 16/600, Pro 600, 630 | 8,800‡ | 9,800‡ |
| VX | 6R905 | HPC3903A | HP LaserJet 5P, 5MP, 6P, 6MP | 4,000‡ | 4,000‡ |
| WX | 6R906 | HPC3909A | HP LaserJet 5si, 5siMX/NX, 5si Mopier, LaserJet 8000, HP240 | 15,000+ | 16,500‡ |
| AX | 6R908 | НРС3906А | HP 5L, 6L, 3100, 3150 | 2,500† | 2,500‡ |
| 62X | 6R925 | C4129X | HP LaserJet 5000, 5000N, 5000DN, 5000GN, 5100 | 10,000† | 10,000‡ |
| 52X | 6R926 | HPC4127X | HP LaserJet 4000, 4000N, 4000T, 4000TN, 4050, 4050N, 4050T, 4050TN, 4050se | 10,000† | 10,000‡ |
| 22X | 6R927 | C4092A | HP LaserJet 1100, 1100se, 1100xi, 1100A, 1100A se, 1100A xi, 3200, 3200se | 2,500† | 2,500‡ |
| 32X | 6R928 | C4096A | HP LaserJet 2100, 2100M, 2100TN, 2100SE, 2100XI, 2200DN, 2200DSE, 2200DT, 2200DTN | 5,000+ | 5,000‡ |
| 72X | 6R929 | C4182X | HP LaserJet 8100, 8100N, 8100DN, 8150, 8150N, 8150DN, 8150HN, 8150MFP | 20,000† | 20,000‡ |
| LJ1200 | 6R932 | C7115X | HP LaserJet 1000, 1200, 1200N, 1200se, 1220, 1220se, 3300MFP, 3310, 3320MFP, 3320NMFP, 3330MFP | 3,500+ | 3,500‡ |
| LJ4100 | 6R933 | C8061X | HP LaserJet 4100, 4100N, 4100TN, 4100DTN, 4100MFP, 4101MFP | 10,000+ | 10,000‡ |
| LJ1150 | 6R956 | Q2624X | HP LaserJet 1150 | 4,000† | 4,000‡ |

^{*}References Canon engine type. **Contains a smart chip to enable smart print functions. †Yields declared in accordance with ISO/IEC 19752 Standard. ‡Yields based on 5 % toner area coverage.

Black-HP, Apple Printer replacement toner supplies

| Machine Type* | Xerox Part Number | Equivalent OEM Part Number | For Use In | OEM Stated Yield | Xerox Stated Yield |
|-------------------------------------|----------------------|-------------------------------|---|------------------------|--------------------------|
| LJ1300 | 6R957 | Q2613X | HP LaserJet 1300, 1300n | 4,000† | 4,000‡ |
| LJ4200** | 6R934 | Q1338A | HP LaserJet 4200, 4200n, 4200tn, 4200dtn, 4200dtns, 4200dtnsl | 12,000‡ | 13,200+ |
| LJ4300/LJ4345mfp** | 6R935 | Q1339A Q5945A | HP LaserJet 4300, 4300n, 4300tn, 4300dtn, 4300dtns, 4300dtnsl, HP LaserJet 4345mfp, 4345x mfp, 4345xm mfp, 4345xs mfp | 18,000‡ | 19,800† |
| LJ2300** | 6R936 | Q2610A | HP LaserJet 2300, 2300d, 2300n, 2300dn, 2300dtn | 6,000† | 6,600† |
| LJ9000** | 6R958 | C8543X | HP LaserJet 9000, 9000n, 9000dn, 9000hns, 9000mfp, 9040mfp, 9050, 9050dn, 9050mfp | 30,000+ | 33,000+ |
| LJ4250/LJ4350** | 6R959 | Q5942X | HP LaserJet 4250, 4250n, 4250tn, 4250dtn, 4250dtnsl HP LaserJet 4350, 4350n, 4350tn, 4350dtn, 4350dtnsl | 20,000+ | 22,000+ |
| LJ2400** | 6R961 | Q6511X | HP LaserJet 2410, 2420, 2420d, 2420dn, 2430, 2430dtn, 2430n, 2430t, 2430tn | 12,000† | 12,000+ |
| LJ1160/LJ1320/ LJ3390** | 6R960 | Q5949A | HP LaserJet 1160, 1320 Series, 3390 Series | 2,500† | 3,500† |
| LJ1320/LJ3390** | 6R1320 | Q5949X | HP LaserJet 1320 Series, 3390 Series | 6,000† | 6,000† |
| LJP2015/LJM2727mfp** | 6R1387 | Q7553X | HP LaserJet P2015 Series, M2727mfp | 7,000† | 7,000† |
| LJP3005/LJM3027mfp/ LJM3035mfp** | 6R1388 | Q7551X | HP LaserJet P3005 Series, M3027mfp, M3035mfp | 13,000† | 13,000+ |
| LJ5200** | 6R1389 | Q7516A | HP LaserJet 5200 Series | 12,000† | 12,000+ |
| LJ1010 | 6R1414 | Q2612A | HP LaserJet 1010, 1012, 1015, 1018, 1020, 1022 Series, 3015, 3030 Series, 3050, 3052, 3055, M1319f mfp | 2,000† | 2,000† |
| LJ1006** | 6R1429 | CB435A | HP LaserJet P1005, P1006 | 1,500† | 1,500† |
| LJ1505** | 6R1430 | CB436A | HP LaserJet P1505, P1505n, M1522n, M1522nf | 2,000+ | 2,000† |
| P4015** Available September | 6R1443 | CC364A | HP LaserJet P4014n, 4015 Series, 4515 Series | 10,000† | 10,000+ |

^{*}References Canon engine type. **Contains a smart chip to enable smart print functions.

[†]Yields declared in accordance with ISO/IEC 19752 Standard. ‡Yields based on 5% toner area coverage.

Brother Laser Printer replacement toner and drum cartridges

| Machine Type | Xerox Part Number | Equivalent OEM Part Number | For Use In | OEM Stated Yield | Xerox Stated Yield |
|--------------|----------------------------|-------------------------------|---|--------------------------|--------------------------|
| HL-2040 | 6R1415 6R1416 | TN350 DR350 | Fax-2820/Fax-2910/Fax-2920/HL-2040/ HL-2070N/DCP-7020/MFC-7220/MFC-7225N/ MFC-7420/MFC-7820N | 2,500 12,500 | 2,500 12,500 |
| HL-5250 | 6R1417 6R1418 6R1419 | TN550 TN580 DR520 | DCP-8060/DCP-8065/DCP-8065DN/HL-5240/ HL-5250DN/HL-5250DNT/HL-5280DW/MFC-8460N/ MFC-8660DN/MFC-8670/MFC-8860DN/MFC-8870DW | 3,500 7,000 25,000 | 3,500 7,000 25,000 |
| HL-1240 | 6R1420 6R1421 6R1422 | TN430 TN460 DR400 | DCP-1200/DCP-1400/Fax-4100/Fax-4100e/Fax-4750/ Fax-4750e/Fax-5750/Fax-5750e/HL-1200/HL-1230/ HL-1240/HL-1250/HL-1270/HL-1435/HL-1440/ HL-1450/HL-1470N/MFC-1260/MFC-8300/MFC-8500/MFC-8600/MFC-8700/MFC-9600/MFC-9700/MFC-9800 | 3,000 6,000 20,000 | 3,000 6,000 20,000 |
| HL-5140 | 6R1423 6R1424 6R1425 | TN540 TN570 DR510 | DCP-8040/DCP-8045D/HL-5100/HL-5140/HL-5150/ HL-5150D/HL-5150DLT/HL-5170DN/HL-5170DNLT/ MFC-8120/MFC-8220/MFC-8440/MFC-8640D/ MFC-8840/MFC-8840D/MFC-8840DN | 3,500 6,700 20,000 | 3,500 6,700 20,000 |

Replacement cartridges

Good for performance and conservation.

Our replacement cartridges keep plastic out of the waste stream. While they contain new and reprocessed components, all critical xerographic components are 100% new. Our cartridges feature Xerox specified and approved toner, as well as new photoreceptors, cleaning blades, certified developer roll sleeves and more.

Triple tested for quality assurance.

To ensure your satisfaction, we constantly monitor manufacturing quality from three sources. First, we print test 100% of all cartridges before packaging. Second, we perform monthly life testing at the manufacturing site. And finally, we test samples from our warehouse inventory in our technical center.

100% risk-free guarantee.

Each replacement cartridge is backed by the Xerox 100% performance guarantee. If you're not satisfied, we're not satisfied. Experience real value that works for you.



For guarantee questions in North America call: 1-866-XEROX-4U

